QUALITY CONTROL

Name of the Work:	Improvements to rd & drains at Abbigere near old watch factory, in W. No. 12
Job No:	012-13-000013
Work order No:	42/12.07.13
BR No:	170/31.05.14

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed Two years back.

Assistant Executive Engineer
Shettyhalli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike